

6387556

1/28

668250-99922260




FIG. 2

2/28

668250" 999222E60





FIG. 2

4/28

668250" 99922E60



IT II □ □ □ □

5/28






FIG. 5




668250-99922E60

7/28



00222660-052896


8/28




09322666-052899

9/28

668250-99922860




11/28



II II II II

09322666-052899


12/28




09322666-052899

11 11 11 11

13/28




14/28



11 11 11 11


09322666-052899

15/28



09322666-052899

16/28




09322666-052899


11 9118

17/28

09322666-052899



18/28




II II II II II

668250-99922660

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN	A23-015	


19/28



09322666-052899

11 11 11 11


20/28



09322666-052899

IEEE 21A


21/28



09322666-052899

11 11 11 11 11


22/28



09322666-052899

Fig 23


23/28



09322566-052899

Illegible signature or stamp

24/28




09322666-052899

IEEE 24/28


25/28

093221666-052899



II II II II II

26/28



09322666-052899

11 11 26

27/28

668250-99922E60





FIG. 27

28/28



093221566-052899